



A	97-08-11	First release.
B	97-09-02	Change J18 from KA53; revise board mounting holes; remove pins from J3 and J7.

C	97-09-10	Move end skewer holes from other side of center; move J2 & J7 closer to corner.
D	97-09-12	Move J2 0.500 right; move J3 0.200 left.
E	97-09-26	Move J7 down 1.548; move J2 from top edge.
F	97-09-29	Move J2, J7, J18 per HDH fax of 970918.
G	97-09-29	Add connector part numbers.

NOTES:

1. Dimensions are in inches.
2. Component side is indicated by a circle with a plus sign.
3. See component side for soldering details.
4. See component side for component side.
5. See component side for component side.
6. See component side for component side.

C. A. Ingraham 1997-08-11

C. A. Ingraham 1997-09-29

C. A. Ingraham

PCB Outline,
MEP DPU EM